

Cerabar PMC131

Absolute And Gauge Pressure

- ◆ Extremely stable, overload-resistant and reliable
- ◆ Measuring range: 100 mbar...40 bar



→ The Cerabar T is a pressure transducer for measuring absolute pressure and gauge pressure in gases, vapors, liquids and dusts.



Accuracy
0,5%

- ⊙ Supply / Communication: 11...30V DC
- ⊙ Process temperature: -20°C...100°C
- ⊙ Output: 4...20mA Analogue