



Level



Pressure



Flow



Temperature



Liquid Analysis



Registration



Systems Components




Services



Solutions

Cerabar T PMP13X

Absolute and Gauge Pressure



➤ **Process connection:**
Threads, Tri-Clamp

➤ **Temperature:** -25°C...100°C

➤ **Power supply :** 12...30V DC

➤ **Output:** 4...20mA analogue

➤ **Max. overpressure limit:** 600 bar (9000psi)

➤ **Measuring range:** 1bar...400bar (15psi...6000psi)

