

RMA42

Process Transmitter With Control Unit



* SIL 2 approval (optional)

* Min./max. value saved

* 5-digit 7-segment LC display, backlit



- ◆ Input: 1 or 2 universal (current, voltage, R, RTD, TC, Ω)
- ◆ Output: 1 or 2 Analog (current, voltage)
- ◆ Relay output: 2 x relay, 1 x Open Collector
- ◆ Operating Voltage: 20-250V AC/DC wide range power supply

